

## Best Practices for Garbing in HD Sterile Compounding

## **DONNING**

## 1. Don a Hair Cover, Face Mask, and Beard Cover



2. Don Double Shoe Covers



3. Perform Hand Hygiene: Clean nails with disposable nail pick. Wet arms and hands up to elbows and lather for 30 seconds.



4. Don Non-Shedding
Regular Gown Followed by
a Chemo Gown



5. Don Two Pairs of Gloves Tested to ASTM 6978 Standard: Apply alcohol-based hand rub and allow to dry immediately prior to each glove.

The first pair of gloves must go under the cuff of the HD Gown. Use the sterile paper to pull down the sleeves and cuffs over the first pair of gloves.





Don the second pair of sterile gloves, this time with the cuff over the HD gown.

